

1. Description:

XY-LUP is an instrument with integrated buck-boost power supply module and multi-function voltage ammeter.

In 'PER' work mode, it can be used as buck-boost power supply module. It can convert to DC 3.5V~12V to DC 1.2V~24V and power is about 2W~3W.

In 'VAH' work mode, it can be used as multi-function voltage ammeter. It can be used to measure voltage, current, power, battery capacity, discharging time.

It is very suitable for technical engineers to develop, debug instrumentation, after-sales engineers travel maintenance, etc.

2. Features:

- 1>.Dual operating system
- 2>.Support power supply output function
- 3>.Support test power supply function
- 4>.Support over power protection
- 5>.LCD high definition display
- 6>.Automatic calibration
- 7>.Multi-parameter simultaneous display
- 8>.Support power saving mode
- 9>.Three voltage input methods
- 10>.Support voltage and current calibration

3. Parameters:

- 1>.Product name: XY-LUP Boost Buck Converter Voltmeter Ammeter;
- 2>.Model: XY-LUP;
- 3>.Work Voltage:DC 3.5V-12V;
- 4>.Output Voltage:DC 1.2V-24V;
- 5>.Output Power:3W(MAX);
Maximum output power within 2W when output DC 1.2V~2V;
Maximum output power within 3W when output DC 2V~20V;
Maximum output power within 2.5W when output DC 20V~24V;
- 6>.Output voltage accuracy: +/-0.5%
- 7>.Output voltage accuracy: +/-1%
- 8>.Measure voltage range:DC 0~35V
- 9>.Measure current range:0~3A
- 10>.Measure power range:0~110W
- 11>.Measure battery capacity range:0~9999Ah
- 12>.Discharging time:0~100hours
- 13>.Work Temperature:-40°C~85°C;
- 14>.Work Humidity:0%~95%RH;
- 15>.Size:77*33*16mm;

4. Mode Switching:

- 1>.The default is the Power Output Mode PER at first;
- 2>.Keep press button 'ON/OFF' to switch mode;
- 3>.When power is remove, module can remembers current operating mode.The default work will be the same mode when power on at next time.

5.Power Output Mode PER:

- 1>.Input from standard USB male socket, Micro USB female socket and 'VIN+/VIN-';
- 2>.Output from 'OUT+' and 'OUT-'.The 'COM' terminal can not be used at PER mode.
- 3>.Rotate the potentiometer to adjust the output voltage;
- 4>.There is a symbol 'OUT' when work in PER mode;
- 5>.Terminal 'COM' unavailable at PER mode;
- 6>.Short press button 'ON/OFF' to turn ON or OFF output voltage.At this time, screen will display 0V.
- 7>.Keep press button 'ON/OFF' for 2 second to switch display output current or output power at the second line.
- 8>.Keep press button 'ON/OFF' for 5 second to turn ON or OFF display screen backlight.But the module can output voltage normally.
- 9>.Keep press button 'ON/OFF' for 10 second to turn switch work mode PER or VAH.
- 10>.The module supports over-power protection. If the rated power is exceeded, the module will automatically stop output voltage and the LCD will display 'OPP' and flash.
- 11>.The module does not support reverse connection protection, please do not short circuit and reverse.

6.Multi-function Meter Mode VAH:

- 1>.Module work voltage : Standard USB male socket, Micro USB female socket and 'VIN+/VIN-' are used to provide work voltage from module.
- 2>.Measuring voltage : 'V' and 'COM' terminals are used to measure Measured Device Voltage.
- 3>.Measuring current : 'A' and 'COM' terminals are used to measure Measured Device Current.
- 4>.Short press button 'ON/OFF' to switch display Measured Device Voltage, Current, Power, Time. And also can measure Battery capacity, Battery discharging time if connect battery.
- 5>.Keep press button 'ON/OFF' for 5 second to turn ON or OFF display screen backlight. But the module can output voltage normally.
- 6>.Keep press button 'ON/OFF' for 10 second to turn switch work mode PER or VAH.
- 7>.The module does not support reverse connection protection, please do not short circuit and reverse.
- 8>.Potentiometer is not available at VAH mode.

7. Calibrate Voltage/Current:

1>. Calibrate Voltage: Keep press button 'ON/OFF' before power ON and then power ON and release button. Automatically enter calibration mode after 5 second. The voltage display will flashing. Short press button to adjust and calibration voltage. Adjustment range is $-0.2V \sim 0.2V$. Enter current calibration mode if keep press button for 2 second.

2>. Calibrate Current: Enter current calibration mode if keep press button for 2 second after Calibrate Voltage. The current display will flashing. Short press button to adjust and calibration voltage. Adjustment range is $-0.02A \sim 0.02A$. Automatically save parameters and return to the normal display interface if keep press button for 5 second.

3>. User needs to repeat the correction multiple times. If the voltage(current) error exceeds $0.2V(0.02A)$.

4>. For example: Change 12V to 12.5V:

4.1>. First calibration: Change 12V to 12.2V

4.2>. Second calibration: Change 12.2V to 12.4V

4.3>. Third calibration: Change 12.4V to 12.5V

8. Use steps:

1>. Connect to power supply from input terminal;

2>. Set work mode by keep press button 'ON/OFF' for 10second;

3>. Connect load or Device Voltage;

4>. Rotate potentiometer to change output voltage if work in PER mode;

5>. Short press button 'ON/OFF' to switch parameter display;

6>. Test and use.

9. Application:

1>. Ordinary low power supply;

2>. Voltmeter;

3>. Ammeter;

4>. Battery capacity tester;

5>. Battery load capacity tester;

10. Note:


1>. The module does not support reverse connection protection, please do not short circuit and reverse.

2>. Adjust the working mode before use.

3>. USB just can input DC 5V. User need input from 'VIN+' and 'VIN-' if input 3.5V-12V.

11. Package:

1>. 1pcs XY-LUP Boost Buck Converter Voltmeter Ammeter;



- 1.Short press button ON/OFF to turn ON or OFF output voltage.At this time, screen will display 0V.
- 2.Keep press button ON/OFF for 2 second to switch display output current or output power at the second line.
- 3.Keep press button ON/OFF for 5 second to turn ON or OFF display screen backlight.But the module can output voltage normally.
- 4.Keep press button ON/OFF for 10 second to turn switch work mode PER or VAH.

It is a low power output power module, please pay attention to the output power.


Maximum output power within 2W when output DC 1.2V~2V;

Maximum output power within 3W when output DC 2V~20V;

Maximum output power within 2.5W when output DC 20V~24V;


The module supports over-power protection. If the rated power is exceeded, the module will automatically stop output voltage and the LCD will display OPP and flash.

PER Mode:Wiring Diagram



VAH Mode


Measure Voltage(0~35V), Current(0~3A), Power(0~110W),
Battery Capacity(0~9999Ah), Discharging Time(0~100h)



- 1.Short press button ON/OFF to switch display Measured Device Voltage,Current, Power,Time.And also can measure Battery capacity,Battery discharging time if connect battery.
- 2.Keep press button ON/OFF for 5 second to turn ON or OFF display screen backlight.But the module can output voltage normally.
- 3.Keep press button ON/OFF for 10 second to turn switch work mode PER or VAH.

The module does not support reverse connection protection, please do not short circuit and reverse.

VAH Mode : Wiring Diagram



Measure Voltage(0~35V), Current(0~3A), Power(0~110W),
Battery Capacity(0~9999Ah), Discharging Time(0~100h)


In VAH work mode, it can be used as multi-function voltage ammeter.


It can be used to measure voltage, current, power, battery capacity, discharging time

Calibrate Voltage/Current



- 1>.Calibrate Voltage:Keep press button ON/OFF before power ON and then power ON and release button.Automatically enter calibration mode after 5 second.The voltage display will flashing.Short press button to adjust and calibration voltage. Adjustment range is $-0.2V\sim 0.2V$.Enter current calibration mode if keep press button for 2 second.
- 2>.Calibrate Current:Enter current calibration mode if keep press button for 2 second after Calibrate Voltage.The current display will flashing.Short press button to adjust and calibration voltage. Adjustment range is $-0.02A\sim 0.02A$. Automatically save parameters and return to the normal display interface if keep press button for 5 second.
- 3>.User needs to repeat the correction multiple times. If the voltage(current) error exceeds $0.2V(0.02A)$.
- 4>.For example:Change 12V to 12.5V:
 - 4.1>.First calibration:Change 12V to 12.2V
 - 4.2>.Second calibration:Change 12.2V to 12.4V
 - 4.3>.Third calibration:Change 12.4V to 12.5V





Measuring voltage


Our XYD5005
DC Power Supply

Measuring voltage

Black table pen connects COM end,
Red table pen connects OUT+(V)

OUT+ (V)

COM



Physical wiring diagram of battery discharge measurement

